	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
1	BRS	L1	46357	pressure and (sensor transducer).ti.	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:32	
2	BRS	L2	1019	1 and sens\$3 near2 (cavity bore)	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:33	
3	BRS	L3	91	2 and bearing	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:34	
4	BRS	L4	124	2 and bear\$3	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 13:50	
5	BRS	L5	0	4 and collet	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:34	
6	BRS	L6	2	2 and collet	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:34	
7	BRS	L8	11	7 and bearing	USPA T; US-P GPUB; DERW ENT	2004/10/0 7 11:38	

	Error Definition	Er ro rs
1		0
2		0
3		0
4		0
5		0
6		0
7		0

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
8	BRS	L7	46	1 and collet	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:42	
9	BRS	L9	4	1 and (collet coller) near3 thread\$3	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:44	
10	BRS	L13	0	10 and 12	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:45	
11	BRS	L10	68	"high pressure sensor".ti.	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:45	
12	BRS	L11	1	10 and (collar collet)	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 11:46	
13	BRS	L12	57	1 and (collet collar) near3 thread\$3	USPA T; US-P GPUB; DERW ENT	2004/10/0 7 14:32	
14	BRS	L14	11	12 and pressure adj (port chamber)	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 13:10	

	Error Definition	Er ro rs
8		0
9		0
10		0
11		O
12		0
13	·	0
14	-	0

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
15	BRS	L15	46	1 and collet	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 13:24	-
16	BRS	L16	11	15 and bearing	USPA T; US-P GPUB ; DERW ENT	2004/10/0 7 13:24	
17	IS&R	L17	1	("5119680").PN.	USPA T	2004/10/0 7 13:50	
18	IS&R	L18	1	("2,679,411").PN.	Т	2004/10/0 7 14:33	
19	BRS	L19	1498	73/756		2004/10/0 7 14:33	
20	BRS	L20	9	19 and collet	USPA T	2004/10/0 7 14:33	

	Error Definition	Er ro rs
15		0
16		0
17		0
18		0
19		0
20		0